

Asset Detail Recommendations

2020-21

Village Buildings:

1. **SALT BARN**- Need a new salt barn!!
2. Village Office – need to reseal the foundation
3. DPW Garage- Needs exterior paint and inspect roof.
4. Village Office- Needs exterior paint and flooring.
5. Visitor's Center Building- Needs interior bead-board added to ceiling and inspect roof.
6. Haserot Park Bathrooms- Doors need to be painted.

Parks:

1. Mill Pond- Schedule dam repairs.
2. South Beach- Needs new post for Volleyball court, wooden structure inspection, and severe shoreline erosion rip-rap needed.
3. Haserot Park- More erosion work needs to be done.

Streets:

1. West Third Street- Culvert needs a condition assessment.
2. East Fourth Street- Add more stone to re-establish road end.
3. West Fourth Street- Resurface road at intersection.
4. West Sixth Street- Resurface road from Mill to Ransom Street.
5. South Shore Drive- Needs resurfacing.

Vehicles and Equipment

1. Stearling Plow Truck- More work needs to be done/ needs replacement